



रोशी गाउँपालिका गाउँ कार्यपालिकाको कार्यालय

रोशी-७, अमलढार, काभ्रेपलाञ्चोक

वागमती प्रदेश, नेपाल



पत्र संख्या : २०८२/०८३

चलानी नं. : ६६५

मिति:- २०८२/०८/२२

विषय: निजी आवास प्रबलीकरण, पुननिर्माण तथा पुनर्स्थापना बारे।

श्री सम्बन्धित सरोकारवालाहरु सबै
रोशी गाउँपालिका।

प्रस्तुत विषयमा मिति २०८१ असोज १० देखि १२ सम्म परेको अविरल वर्षाको कारणले आएको बाढीपहिरोबाट पूर्ण रुपमा क्षति भएका वा आंशिक रुपमा क्षति भएको भएता पनि बस्न नमिल्ने भएका निजी आवासका घर घरपरिवारको विस्तृत क्षति आँकलन DDA (Detail Damage Assesment) समेत भैसकेको र उक्त आँकलनबाट निजी आवास प्रबलीकरण, पुननिर्माण तथा पुनर्स्थापनाका लागि कायम भएका लाभग्राहीहरुको विवरण तपसिल बमोजिम रहेको व्यहोरा जानकारीको लागि अनुरोध छ।

बोधार्थ

श्री वडा कार्यालय सबै (१ देखि १२)
रोशी गाउँपालिका, काभ्रेपलाञ्चोक।

(टंक बहादुर नेगी)

प्रमुख प्रशासकीय अधिकृत

टंक बहादुर नेगी

प्रमुख प्रशासकीय अधिकृत



क्र.स	स्थानिय तह	वडा नं.	लाभग्राहीको नाम	सुबा/श्रीमानको नाम	Comments	damage_grade	grade_category	श्रेणी वर्ग
1	Roshi	1	(Kamal Tamang) कमल तामाङ		have other house with fully damaged.	5	Reconstruction	पुनर्निर्माण
2	Roshi	1	कान्छा गोले	श्री इमानसिं गोले		5	Reconstruction	पुनर्निर्माण
3	Roshi	1	राम चन्द्र सुनुवार	श्री क्षेत्र बहादुर सुनुवार		5	Reconstruction	पुनर्निर्माण
4	Roshi	1	किरण वि क	श्री खड्ग बहादुर कामी		5	Reconstruction	पुनर्निर्माण
5	Roshi	1	रविन कामी	श्री खड्ग बहादुर कामी	Debris was deposited inside the house ,walls were damaged ,now it is repaired but the building is in risk site of landslide .Front of building is in risk of landslide	2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
6	Roshi	1	कुमार कामी	श्री खड्ग बहादुर कामी		2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
7	Roshi	1	गोपी लाल श्रेष्ठ	श्री लाल बहादुर श्रेष्ठ		5	Reconstruction	पुनर्निर्माण
8	Roshi	1	सुमन गोले	श्री इन्द्र बहादुर गोले		5	Reconstruction	पुनर्निर्माण
9	Roshi	1	काईला गोले	श्री कमान सिं गोले		5	Reconstruction	पुनर्निर्माण
10	Roshi	1	Sarki Man Lama			1	Not Required	
11	Roshi	1	आइत लाल नगरकोटी	श्री गणेश नगरकोटी		5	Reconstruction	पुनर्निर्माण
12	Roshi	1	राज मान लामा	श्री सुब्बा सिं लामा	Surveyor = DG2 Reviewer = DG1	2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
13	Roshi	1	नर बहादुर सुनार	श्री जस निर सुनार		5	Reconstruction	पुनर्निर्माण
14	Roshi	1	बलराम गुरुङ	श्री लाल बहादुर गुरुङ		5	Reconstruction	पुनर्निर्माण
15	Roshi	1	जगतमान लामा	श्री मित्रमान लामा		5	Reconstruction	पुनर्निर्माण
16	Roshi	1	माया तामाङ	श्री मान बहादुर तामाङ		5	Reconstruction	पुनर्निर्माण
17	Roshi	1	विजय विश्वकर्मा	श्री गोपी बहादुर विश्वकर्मा		5	Reconstruction	पुनर्निर्माण
18	Roshi	1	कुमार लामा	श्री सानु लामा		5	Reconstruction	पुनर्निर्माण
19	Roshi	1	सोवित सिं न्यासुर	श्री कान्छामान लामा	have other house with partial damage.	1	Not Required	आवश्यक छैन
20	Roshi	1	कर्ण बहादुर लामा	श्री गणेश सिंह लामा	have other house with partial damage.	1	Not Required	आवश्यक छैन
21	Roshi	1	बाबु लाल	श्री कोपिल कृष्ण		5	Reconstruction	पुनर्निर्माण
22	Roshi	1	न्हुछे लाल	श्री कोपिल कृष्ण		5	Reconstruction	पुनर्निर्माण
23	Roshi	1	इन्द्र बहादुर सुनार	श्री जसबिर सुनुवार		5	Reconstruction	पुनर्निर्माण
24	Roshi	1	भिम बहादुर सुनार	श्री जसबिर सुनुवार		5	Reconstruction	पुनर्निर्माण
25	Roshi	1	तेज बहादुर	श्री जसमान सिं		5	Reconstruction	पुनर्निर्माण
26	Roshi	1	हरीबहादुर लोप्चन	श्री जसमान सिं लोप्चन		5	Reconstruction	पुनर्निर्माण
27	Roshi	1	हर्क बहादुर	श्री जस विर सुनुवार		1	Not Required	पुनर्निर्माण
28	Roshi	1	गणेश बहादुर श्रेष्ठ	श्री कोपिल कृष्ण श्रेष्ठ		5	Reconstruction	पुनर्निर्माण
29	Roshi	1	टक बहादुर सुनार	श्री जसबिर सुनार		5	Reconstruction	पुनर्निर्माण

क्र.स	स्थानिय तह	वडा नं.	बुबा/श्रीमानको नाम	लाभग्राहीको नाम	comments	damage_grade	grade_category	श्रेणी वर्ग
1	Roshi	2	श्री पुर्ण सिंह बल	(pancha Lala Bal)		1	Not Required	आवश्यक छैन
2	Roshi	2	श्री दुलो बाबु कामी	शरोज कामी		1	Not Required	आवश्यक छैन
3	Roshi	2	श्री दुलो बाबु कामी	जनक विश्वकर्मा		1	Not Required	आवश्यक छैन
4	Roshi	2	श्री धर्म ध्वज लामा	सत्य मान लामा		1	Not Required	आवश्यक छैन
5	Roshi	2	श्री काजीमान लामा	विकास लामा		1	Not Required	आवश्यक छैन
6	Roshi	2	श्री पुर्ण सिंह लामा	टिका बहादुर लामा		1	Not Required	आवश्यक छैन
7	Roshi	2	श्री भोरासमान लामा	तिर्थ बहादुर लामा		1	Not Required	आवश्यक छैन
8	Roshi	2	श्री मान बहादुर लामा	साइला काजी लामा		4	Reconstruction	पुनर्निर्माण
9	Roshi	2	श्री जित बहादुर लामा	बाबु लामा	As per surveyor the house was 2 storey before disaster and top floor is fully damage	4	Reconstruction	पुनर्निर्माण
10	Roshi	2	श्री ललीत बहादुर बोहरा	पदम बहादुर बोहरा क्षेत्री		5	Reconstruction	पुनर्निर्माण
11	Roshi	2	श्री खन्ड सिंह लामा	प्रताप सिंह लामा		5	Reconstruction	पुनर्निर्माण
12	Roshi	2	श्री नन्दराज लामा	सूर्य लामा		1	Not Required	आवश्यक छैन
13	Roshi	2	श्री कर्तीराज लामा	वृद्धराज लामा		1	Not Required	आवश्यक छैन
14	Roshi	2	श्री कामी सिंह तामाङ	माईली तामाङनी		1	Not Required	आवश्यक छैन
15	Roshi	2	श्री सुब्बा सिंह लो	हिरा माया लामा	On basis of selection repaired and occupied DG1 is accepted	1	Not Required	आवश्यक छैन
16	Roshi	2	श्री लिला बहादुर थापा	अम्बर बहादुर थापा		4	Reconstruction	पुनर्निर्माण
17	Roshi	2	श्री दौलत सिंह	धन सिंह लामा		4	Reconstruction	पुनर्निर्माण
18	Roshi	2	श्री विश्व विक्रम बोहरा	शान्ता बोहरा		5	Reconstruction	पुनर्निर्माण
19	Roshi	2	श्री कृष्ण हरि खत्री	राम कुमार के सी		5	Reconstruction	पुनर्निर्माण
20	Roshi	2	श्री जगत राम	मान कुमारी दमै		5	Reconstruction	पुनर्निर्माण
21	Roshi	2	श्री आत्मा राम	माईला लामा		1	Not Required	आवश्यक छैन
22	Roshi	2	श्री राम बहादुर लामा	आशा लामा		1	Not Required	आवश्यक छैन
23	Roshi	2	श्री राज बल	फुलमाया तामाङ		5	Reconstruction	पुनर्निर्माण
24	Roshi	2	श्री हेम बहादुर सिन्धुरी	युवराज सिन्धुरी	The damage grade is OK. However, Special attention is required regarding the geotechnical investigation of the site, and resettlement may be necessary.	2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
25	Roshi	2	श्री हिराकाजी लामा	समिर लामा		5	Reconstruction	पुनर्निर्माण
26	Roshi	2	श्री जगत बहादुर	उमेश बहादुर श्रेष्ठ		5	Reconstruction	पुनर्निर्माण
27	Roshi	2	श्री पदम बहादुर बोहोरा क्षेत्री	राजन बोहोरा क्षेत्री		5	Reconstruction	पुनर्निर्माण
28	Roshi	2	श्री वल बहादुर राय	चेत बहादुर राय		5	Reconstruction	पुनर्निर्माण
29	Roshi	2	श्री हस्त बहादुर	केस बहादुर सिनचिउरी	The form and evidence shows NO DAMAGE but further geological and geotechnical investigation is required for site.	1	Not Required	
30	Roshi	2	श्री पदम बहादुर सिनचिउरी	ईन्द्र बहादुर सिनचिउरी		5	Reconstruction	पुनर्निर्माण

31	Roshi	2	श्री काईला लामा	च्यामा लामा	One floor has been damaged and is unusable.	4	Reconstruction	पुनर्निर्माण
32	Roshi	2	श्री पञ्च लाल लोप्चन	देवी माया पाख्रिन		5	Reconstruction	पुनर्निर्माण
33	Roshi	2	श्री हस्त बहादुर सिनचिउरी	चेन बहादुर सिनचिउरी	Building Damage Grade DG1 is acceptable, but further geotechnical and geological investigations may be necessary.	1	Not Required	आवश्यक छैन
34	Roshi	2	श्री लोक बहादुर बोहोरा	लोक नाथ बोहोरा	Building Damage Grade DG1 is acceptable, but further geotechnical and geological investigations may be necessary.	1	Not Required	आवश्यक छैन
35	Roshi	2	श्री प्रकाश बोहोरा	भवानी बोहोरा		5	Reconstruction	पुनर्निर्माण
36	Roshi	2	श्री क्षेत्र बहादुर सुनुवार	सुवत्र सिन्दुरी		4	Reconstruction	पुनर्निर्माण



क्र.स	स्थानिय तह	वडा नं.	बुबा/श्रीमानको नाम	लाभग्राहीको नाम	comments	damage_grade	grade_category	श्रेणी वर्ग
1	Roshi	3	श्री सोभितमान लामा	गंगा बहादुर लामा	As per surveyor "Building is not damage and it is not occupied because of psychology pressure Landslide evidence is found in u/s of building."	1	Not Required	आवश्यक छैन
2	Roshi	3	श्री काहीला लामा	राज कुमार लामा	As per surveyor "Building is not affected by landslide But is in high risk as fissure is visible in right side of building." So, Geotechnical Investigation is Recommended.	1	Not Required	आवश्यक छैन
3	Roshi	3	श्री भिम बहादुर श्रेष्ठ	जगत माया श्रेष्ठ		1	Not Required	आवश्यक छैन
4	Roshi	3	श्री पदम बहादुर तुम्सीङ मगर	(Dil Bhadur Magar)दिल बहादुर तुम्सीङ मगर	As per surveyor "Though building has not been affected by landslide, it is in the high risk of landslide. There is evidence sign of landslide in the right side of building. It is recommended to relocate them because it is not safe to stay in this location. According to responded: There is fissure in U/S of building. Though we cannot verify this because of harsh geography. " So, geotechnical investigation of site is recommended.	1	Not Required	आवश्यक छैन
5	Roshi	3	श्री लोक बहादुर	(Bhoj Bhadur Pulami Magar)भोज बहादुर पुलामी मगर	As per surveyor "Though this building is not affected flood. But it is not feasible to occupy building as there is landslide just d/s and right side of building. It is not safe to stay in this location. Since they have no any other land, they want to stay in same location. However it is highly recommended to shift them to a safer location. Family don't have any source of income expect daily wages. Villagers and relative are supporting them financially." So, Geotechnical Investigation is recommended.	1	Not Required	
6	Roshi	3	श्री गुमान सि	मोहन सि ठोकर		1	Not Required	आवश्यक छैन
7	Roshi	3	श्री कुमार लामा	सानु माया लामा		1	Not Required	आवश्यक छैन
8	Roshi	3	श्री दुल्लो कान्छा थापा मगर	रोहित थापा मगर		5	Reconstruction	पुनर्निर्माण
9	Roshi	3	श्री अक्कल बहादुर मगर	दुल्लो कान्छो थापा मगर		5	Reconstruction	पुनर्निर्माण
10	Roshi	3	श्री मान बहादुर	सुरेश पुलामी मगर	As per surveyor "there is a small landslide 2 m away from the corner of the house." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	आवश्यक छैन
11	Roshi	3	श्री रामबहादुर मगर	मानबहादुर		1	Not Required	आवश्यक छैन
12	Roshi	3	श्री टंकबहादुर	बिर बहादुर	GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	आवश्यक छैन



13	Roshi	3	श्री माईलाकाजी तामाङ	कुमार सि तामाङ	As per surveyor "The building looks fine now. There is small landslide at 20 m from the building. This landslide is likely to cause debris flow in future so needs to be checked. The building was shaken by earthquake and has been repaired. As per respondent, at the time of flooding a large tree from the landslide had hit the house causing the back wall to collapse. Though this has been repaired now, the owner feels unsafe to reside in this house hence wants to build a new safer house in this safe location." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	2	Minor Retrofit (Category 1)	
14	Roshi	3	श्री धनविर लामा	पंच माया तामाङनी	As per surveyor "The building itself is not damaged but there is a huge landslide at the back of building. The landslide needs to be checked to the earliest to protect the building in future." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	
15	Roshi	3	श्री बुद्धिमान	च्यमा लामा		1	Not Required	आवश्यक छैन
16	Roshi	3	श्री कुल बहादुर श्रेष्ठ	बाल कृष्ण श्रेष्ठ		5	Reconstruction	पुनर्निर्माण
17	Roshi	3	श्री कामि सि	कृष्ण बहादुर थिङ		2	Minor Retrofit (Category 1)	
18	Roshi	3	श्री चन्द्र बहादुर मगर	कृष्ण बहादुर मगर	As per surveyor "Building is not affected by landslide, However Building is in high risk of landslide. Fissure is also evident in u/s of building." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED	1	Not Required	आवश्यक छैन
19	Roshi	3	श्री धन बहादुर राना मगर	लोक बहादुर राना मगर	As per surveyor "Building is not affected by landslide but is in high risk of landslide." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED	1	Not Required	आवश्यक छैन
20	Roshi	3	श्री भोज बहादुर थापा मगर	इन्द्र बहादुर थापा मगर	Building is completely covered by debris from outside. Only way to enter home is from roof side. Debris was accumulated inside the house also but now is removed. Building is in risk of collapse because of lateral pressure. Crack is seen in all side of building. And it may grow with the time.	4	Reconstruction	पुनर्निर्माण
21	Roshi	3	श्री राम सि मुक्तान लामा	कान्छा मान मुक्तान लामा		5	Reconstruction	पुनर्निर्माण
22	Roshi	3	श्री चितमान	लालमान		1	Not Required	आवश्यक छैन
23	Roshi	3	श्री तुला बहादुर ठाडा मगर	देव बहादुर ठाडा मगर		5	Reconstruction	पुनर्निर्माण
24	Roshi	3	श्री खड्ग बहादुर मगर	उत्तल बहादुर मगर		1	Not Required	आवश्यक छैन
25	Roshi	3	श्री लोक बहादुर तुम्सिङ	रूप बहादुर तुम्सिङ		5	Reconstruction	पुनर्निर्माण
26	Roshi	3	श्री दुलो कान्छा मगर	नारन पुलामी मगर		1	Not Required	आवश्यक छैन



27	Roshi	3	श्री रत्न बहादुर आले मगर	ठकुरा कुमारी मगर	As per surveyor "The house is under construction. Door and window are yet to be fit. There is no structural damage to the building but building is filled with debris. Additional, building is located at high risk of landslide." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED	1	Not Required	आवश्यक छैन
28	Roshi	3	श्री बुद्धिविर तुम्सीङ मगर	रुद्र बहादुर तुम्सीङ मगर	As per surveyor "Building is not affected at all. Neither here is any evidence of future landslide or flood."	1	Not Required	
29	Roshi	3	श्री तिलक बहादुर मगर	नेत्र बहादुर मगर		5	Reconstruction	पुनर्निर्माण
30	Roshi	3	श्री नन्द बहादुर मगर	लक्ष्मी माया मगर		1	Not Required	आवश्यक छैन
31	Roshi	3	श्री कृष्ण हरि मगर	विष्णुकाजी मगर	As per surveyor "Building is not affected by landslide but has the high risk in landslide in coming monsoon. According to responded. Fissure is present in w/s of building. Though we cannot verify this because of harsh geography." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED	1	Not Required	आवश्यक छैन
32	Roshi	3	श्री गोविन्द	तिलक बहादुर मगर		5	Reconstruction	पुनर्निर्माण
33	Roshi	3	श्री दिप्य बहादुर मगर	टेक बहादुर मगर		5	Reconstruction	पुनर्निर्माण
34	Roshi	3	श्री दल बहादुर तुमर्सि	लोक बहादुर तुमर्सि		5	Reconstruction	पुनर्निर्माण
35	Roshi	3	श्री टेक बहादुर तुम्सीङ मगर	कुमार तुम्सीङ मगर	As per surveyor "The itself is safe. No visible distress is seen. There is a landslide nearby (around 5). This slide does not seem to pose any immediate danger but future possibility cannot be denied if it remains unprotected. Responder did not report any other concerns." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	आवश्यक छैन
36	Roshi	3	श्री टेक बहादुर थापा मगर	सुर्य बहादुर मगर		5	Reconstruction	पुनर्निर्माण
37	Roshi	3		Bhagawan Tumsing Magar	As per surveyor "At present no risk of landslide is seen in near by location but entire geology of settlement looks vulnerable, that should be checked." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	आवश्यक छैन
38	Roshi	3	श्री पद्म बहादुर तुम्सीङ मगर	दिल बहादुर तुम्सीङ मगर		1	Not Required	आवश्यक छैन
39	Roshi	3	श्री ज्ञान प्रसाद काप्ले	भगवती अधिकारी	The damage grade is DG4	5	Reconstruction	पुनर्निर्माण



40	Roshi	3	श्री श्याम सुन्दर कार्की	रमा कुमारी कार्की	According to surveyor "Building is not affected by landslide but is in high verse of collapse in coming monsoon. According to respondent: Ground u/s to the building is cracked and has high probability of sliding in coming monsoon. Although we cannot verify this because of harsh geography." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED	1	Not Required	आवश्यक छैन
41	Roshi	3	श्री मान बहादुर	साइला लामा	As per surveyor "Building is in construction phase and Back wall of building is completely collapsed. But since building is frame structure and there is no damage in frame structure so it's safe to reconstruct again. Proper geological survey is required as u/s of building has high probability of landslide. House owner has another building too. But that building is also partially damage due to earthquake." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED	3	Major Retrofit (Category 2)	
42	Roshi	3	श्री मोहन सिंह लामा	जोगमान लामा	As per surveyor "Building is not affected by landslide which is in the upstream. Yet a house built at head of landslide poses significant risk to the house assessed." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED	1	Not Required	आवश्यक छैन
43	Roshi	3	श्री राम बहादुर लामा	साइला लोन्बन	As per surveyor "Building is not affected by landslide. But has high probability of facing severe damage in coming monsoon. As d/s of building has evident sign of landslide." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED	1	Not Required	आवश्यक छैन
44	Roshi	3	श्री साइला काजी लोन्बन	सोनम लोन्बन		5	Reconstruction	पुनर्निर्माण
45	Roshi	3	श्री इन्द्रमान लामा	विमला लामा	Building is not affected by flood but has high risk of landslide. GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	आवश्यक छैन
46	Roshi	3	श्री कृष्ण बहादुर बल	शेर बहादुर बल	DG is accepted. The house is incomplete. No any damage in building. It has small landslide at the right side of building at approx 5 m away, which is the main risk to the building seen at site. GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	आवश्यक छैन
47	Roshi	3	श्री सीध बिर् लामा	निर्मला लामा		5	Reconstruction	पुनर्निर्माण
48	Roshi	3	श्री ईन्द्र मान लामा	चन्द्र सिंह लामा		1	Not Required	आवश्यक छैन



49	Roshi	3	श्री ईन्द्रमान लामा	आइता सि लामा		1	Not Required	आवश्यक छैन
50	Roshi	3	श्री खण्ड सि	रानी माया लोप्चन	As per surveyor "Bulging is seen in back side of building. Building was covered with debris about 3-4 feet. Floor was also scoured at that time but repaired afterwards by own."	2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
51	Roshi	3	श्री शंखविर लामा	पासाङ	As per surveyor "Building was completely collapsed and reconstructed and consecrated. Note: Building lies in the high risk of landslide. According to respondent: Fissure is at u/s of building but we cannot reach and verify because of harsh geography." SO, GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED	5	Reconstruction	पुनर्निर्माण
52	Roshi	3	श्री चलान सि तामाङ	कृष्ण बहादुर वल तामाङ	GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	
53	Roshi	3	श्री सुप सि लामा	जित बहादुर लामा	GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	आवश्यक छैन
54	Roshi	3	श्री संख विर लामा	कुमार लामा	As per surveyor "The house was affected by landslide, which is still active so landslide protection measure needs to be in place." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	आवश्यक छैन
55	Roshi	3	श्री तिलक बहादुर थापा	देवि बहादुर थापा क्षेत्री	As per surveyor "There is no damage to building but building is in high risk of landslide. Land slide had occurred at downstream of of building at 2m horizontal distance from building. There is evidence of landslide in up stream too. Though this house is not affected this time but is in high risk of vulnerability in upcoming monsoon.", There is no damage to building but building is in high risk of landslide. Land slide had occurred at downstream of of building at 2m horizontal distance from building. There is evidence of landslide in up stream too. Though this house is not affected this time but is in high risk of vulnerability in upcoming monsoon. , As per surveyor "There is no damage to building but building is in high risk of	1	Not Required	



56	Roshi	3	श्री एक बहादुर बोहरा	(Nirmala Thapa)निर्मला थापा	As per surveyor "There is no damage to building but building is in high risk of landslide. Land slide had occurred at downstream of of building at 2m horizontal distance from building. There is evidence of landslide in up stream too. Though this house is not affected this time but is in high risk of vulnerability in upcoming monsoon."	1	Not Required	आवश्यक छैन
57	Roshi	3			As per surveyor " Thought the building is not damage now but site is very susceptible to landslide hazard . The distance between building and landslide is 2 meter "	1	Not Required	
			श्री कुलमान लामा	माइला लामा				
58	Roshi	3	श्री बुद्धिमान लामा	ईन्द्र मान लामा	As per surveyor "Building was collapsed and rebuild by own ."	5	Reconstruction	पुनर्निर्माण
59	Roshi	3	श्री धन बहादुर लामा	माया	As this building is rebuilt	5	Reconstruction	पुनर्निर्माण
60	Roshi	3	श्री इन्द्र सिंह लामा	पुर्णमान लामा		5	Reconstruction	पुनर्निर्माण
61	Roshi	3	श्री च्याङ्बा सि तामाङ	आशिष तामाङ		4	Reconstruction	पुनर्निर्माण
62	Roshi	3	श्री गम्भीर सि	कान्छी तामाङनी		5	Reconstruction	पुनर्निर्माण
63	Roshi	3	श्री विरा सि लामा	राम लामा		1	Not Required	आवश्यक छैन
64	Roshi	3		Pote Sya		1	Not Required	आवश्यक छैन
65	Roshi	3	श्री बित्त मान लामा	कान्छा लामा		1	Not Required	आवश्यक छैन
66	Roshi	3	श्री धर्मलाल तामाङ	विष्णुमाया लामा		1	Not Required	आवश्यक छैन
67	Roshi	3	श्री पुर्णमान लामा	उत्तर सि लामा		3	Major Retrofit (Category 2)	प्रबलीकरण(समुह २)
68	Roshi	3			As per surveyor "There is no visible damage to the building. No major cracks were seen. The respondent said the floor was settled, which she repaired and isn't visible now. But the house is not occupied because of landslide just beneath the house. One of foundation is little exposed." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	आवश्यक छैन
			श्री भरत सि लामा	विन्दु माया लामा				



क्र.स	स्थानिय त	वडा न.	बुबा/श्रीमानको नाम	लाभग्राहीको नाम	comments	damage_grade	grade_category	श्रेणी वर्ग
1	Roshi	4	श्री रेशम ब. राना मगर	नवराज राना मगर	Repaired and occupied. Completely roof damaged and building is filled with debris which is now cleared and temporarily roof is set up and now used as shed.	3	Major Retrofit (Category 2)	प्रबलीकरण(समुह २)
2	Roshi	4	श्री धान बहादुर मगर	ज्ञान बहादुर राना मगर		1	Not Required	आवश्यक छैन
3	Roshi	4	श्री चन्द्रमान तामाङ	सोम बहादुर तामाङ	landslide prone area.	5	Reconstruction	पुनर्निर्माण
4	Roshi	4	श्री खड्ग बहादुर ठाडामगर	प्रवीण ठाडामगर	The wall was rebuilt in one side	3	Major Retrofit (Category 2)	प्रबलीकरण(समुह २)
5	Roshi	4	श्री चन्द्र ब ठाडा	खड्ग बहादुर ठाडा मगर		5	Reconstruction	पुनर्निर्माण
6	Roshi	4	श्री हरी बहादुर मगर	राम्री मगर		1	Not Required	आवश्यक छैन
7	Roshi	4	श्री अम्बर बहादुर मगर	बेनि बहादुर राणा मगर		2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
8	Roshi	4	श्री राम बहादुर राना	हरी माया मगर		2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
9	Roshi	4	श्री कर्णबहादुर थापा मगर	तिलकबहादुर थापा		1	Not Required	आवश्यक छैन
10	Roshi	4	श्री हिरा मान तामाङ	लासाङ माया तामाङ		3	Major Retrofit (Category 2)	प्रबलीकरण(समुह २)
11	Roshi	4	श्री चन्द्र बहादुर यस्माली	मैया यस्माली	have other house with fully damaged.	5	Reconstruction	पुनर्निर्माण
12	Roshi	4	श्री श्याम बहादुर तामाङ	सविन तामाङ	have other house with fully damage.	5	Reconstruction	पुनर्निर्माण
13	Roshi	4	श्री दुर्गा बहादुर मगर	धनकुमार यस्माली मगर		5	Reconstruction	पुनर्निर्माण
14	Roshi	4	श्री हरि बहादुर मगर	गुञ्ज बहादुर मगर	have other house with fully damaged. seem it lies in river bed/ high flood level area. , have other house with fully damaged.	5	Reconstruction	पुनर्निर्माण
15	Roshi	4	श्री लाल ब. तामाङ	दल बहादुर तामाङ	have other house with fully damage. It seems that the building lies in river bed/high flood level.	5	Reconstruction	पुनर्निर्माण
16	Roshi	4	श्री तारामाया राना मगर	कुष्ण राना मगर	the house lies near the river bed which washed out the flood plain and which washed the house completely	5	Reconstruction	पुनर्निर्माण
17	Roshi	4	श्री जित ब थापा	दिल बहादुर थापा मगर		5	Reconstruction	पुनर्निर्माण
18	Roshi	4	श्री नरमान लामा	लुलङ लामिनि		1	Not Required	आवश्यक छैन
19	Roshi	4	श्री हस्त बहादुर तामाङ	कमला तामाङ	Damaged but debris not cleared	5	Reconstruction	पुनर्निर्माण
20	Roshi	4	श्री धन मान तामाङ	ज्ञान बहादुर तामाङ	Damaged but debris not cleared	5	Reconstruction	पुनर्निर्माण
21	Roshi	4	श्री दुलाँ कान्छा लामा	रत्न माया तामाङ	The house is completely swiped by the flood.	5	Reconstruction	पुनर्निर्माण
22	Roshi	4	श्री हर्कमान तामाङ	गुमान सिंह तामाङ	But, The area is in a vulnerable position.(risk of active landslide). high risk of foundation scouring below. GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED	1	Not Required	आवश्यक छैन



क्र.स	स्थानिय तह	वडा नं.	बुवा/श्रीमानको नाम	लाभग्राहीको नाम	comments	damage_grade	grade_category	श्रेणी वर्ग
1	Roshi	5	श्री काजी मान लामा	छाेइसङ दोर्जे लामा	The damage grade is OK. Further investigation for Landslide is recommended	2	Minor Retrofit (Category 1)	प्रबल्लीकरण(समुह १)
2	Roshi	5	श्री पन्चा व. लामा	हिरा बहादुर लामा		1	Not Required	आवश्यक छैन
3	Roshi	5	श्री पदम बहादुर लामा	निर बहादुर लामा		1	Not Required	आवश्यक छैन
4	Roshi	5	श्री कृष्ण राज लामा	सिता माया लामा		5	Reconstruction	पुनर्निर्माण
5	Roshi	5	श्री रूप बहादुर लामा	मान बहादुर लामा	The damage grade is OK. Further site investigation for Landslide is recommended	1	Not Required	आवश्यक छैन
6	Roshi	5	श्री बखान सिंह लामा	हरि माया तामाङ		1	Not Required	आवश्यक छैन
7	Roshi	5	श्री गन बहादुर लामा	विष्णु माया लामिनि		1	Not Required	आवश्यक छैन
8	Roshi	5	श्री कृष्ण बहादुर तामाङ	सुरविर तामाङ		5	Reconstruction	पुनर्निर्माण
9	Roshi	5	श्री नारायण सिंह रुम्बा	गुनमाया लामा		5	Reconstruction	पुनर्निर्माण
10	Roshi	5	श्री दबाङचु लामा	लक्ष्मी माया लामा		1	Not Required	आवश्यक छैन
11	Roshi	5	श्री बाग सिंह लामा	जित बहादुर लामा	The damage grade is OK. Further urgent investigation for Landslide is recommended	1	Not Required	आवश्यक छैन
12	Roshi	5	श्री काइला लामा	अमृत सिंह तामाङ	Urgent geotechnical investigation is recommended as per surveyor "Building is not affected visibly but the compound is totally damaged that might have affect building foundation."	1	Not Required	आवश्यक छैन
13	Roshi	5	श्री नोर्बु सिंह लामा	विर बहादुर लामा		3	Major Retrofit (Category 2)	प्रबल्लीकरण(समुह २)
14	Roshi	5	श्री खड्का बहादुर विष्टकर्मा	पदम बहादुर विष्टकर्मा		1	Not Required	आवश्यक छैन
15	Roshi	5	श्री पदम बहादुर विष्टकर्मा	कमल विष्टकर्मा		2	Minor Retrofit (Category 1)	प्रबल्लीकरण(समुह १)
16	Roshi	5	श्री ठकुर विष्टकर्मा	अर्जुन विष्टकर्मा	Building is unaffected by landslide but the building site is prone to landslide. Land near back of building is washed by landslide As per surveyor	1	Not Required	आवश्यक छैन
17	Roshi	5	श्री सुर्व बहादुर पलान तामाङ	जेम बहादुर पलान तामाङ	Building is unaffected by landslide but the building site is prone to landslide. Land near back of building is washed by landslide	1	Not Required	आवश्यक छैन
18	Roshi	5	श्री मान बहादुर बाइवा	भीम बहादुर बाइवा		5	Reconstruction	पुनर्निर्माण



क्र.स	स्थानिय तह	वडा नं.	बुबा/श्रीमानको नाम	लाभग्राहीको नाम	comments	damag e_grad e	grade_category	श्रेणी वर्ग
1	Roshi	6	श्री सङ्ख सिं पाख्रिन लामा	खड्ग बहादुर पाख्रिन लामा		5	Reconstruction	पुनर्निर्माण
2	Roshi	6	श्री जितमान तामाङ	पुर्ण मान तामाङ		3	Major Retrofit (Category	प्रबलीकरण(समुह २)
3	Roshi	6	श्री काजी मान तामाङ	कान्छि माया तामाङ		3	Major Retrofit (Category	प्रबलीकरण(समुह २)
4	Roshi	6	श्री ज्ञान बहादुर तामाङ	मसु तामाङनी		5	Reconstruction	पुनर्निर्माण
5	Roshi	6	श्री साईला लोप्चन	प्रेम बहादुर तामाङ	Damaged, debris removed and re-built (or re- building)	5	Reconstruction	पुनर्निर्माण
6	Roshi	6	श्री मोहन प्रसाद रेग्मी	प्रमोद रेग्मी	Damaged but debris not cleared	5	Reconstruction	पुनर्निर्माण
7	Roshi	6	श्री खडानन्द मैनाली	नारायणप्रसाद मैनाली	DG2 verified. But the surveyor comment "The house was collapsed and rebuilt." does not support from evidence.	2	Minor Retrofit (Category	प्रबलीकरण(समुह १)
8	Roshi	6	श्री चन्द्र कान्त	कान्छा सिवभक्ती	have other house with no damage.	1	Not Required	आवश्यक छैन
9	Roshi	6	श्री रेवती मैनाली	गंगा मैनाली	Completely collapsed and fully burried.	5	Reconstruction	पुनर्निर्माण
10	Roshi	6	श्री कृष्ण बहादुर सिवभक्ती	काईला सिवभक्ती		5	Reconstruction	पुनर्निर्माण
11	Roshi	6	श्री कान्छा सिवभक्ती	सुन्दर सिवभक्ती	Collapsed or Near Collapsed	5	Reconstruction	पुनर्निर्माण
12	Roshi	6	श्री साईला लोप्चन	प्रेम बहादुर तामाङ		5	Reconstruction	पुनर्निर्माण
13	Roshi	6	श्री प्रेमध्वज लामा	अशोक लामा	The building is of damage grade DG4	5	Reconstruction	पुनर्निर्माण
14	Roshi	6	श्री माइला लामा	उमेश लामा		3	Major Retrofit (Category	प्रबलीकरण(समुह २)
15	Roshi	6	श्री सिव प्रसाद भण्डारी	नारायण प्रसाद भण्डारी	The damage grade is approved but as per surveyor "possible soil erosion downhill which can affect the foundation of the house. retaining wall can prevent from ground displacement." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED	1	Not Required	आवश्यक छैन
16	Roshi	6	श्री संग्राम सिं तामाङ	काइला तामाङ		5	Reconstruction	पुनर्निर्माण
17	Roshi	6	श्री सिव प्रसाद भण्डारी	कृष्ण प्रसाद भण्डारी	inclined more than 2 degrees	5	Reconstruction	पुनर्निर्माण



क्र.स	स्थानिय तह	वडा नं.	बुबा/श्रीमानको नाम	लाभग्राहीको नाम	comments	damage_grade	grade_category	श्रेणी वर्ग
1	Roshi	7	श्री थिङ साइला	धन बहादुर थिङ		5	Reconstruction	पुनर्निर्माण
2	Roshi	7	श्री कामी सिं तामाङ	सानुकान्छी तामाङनी	building lies in active land slide.	1	Not Required	आवश्यक छैन
3	Roshi	7	श्री सोधितमान तामाङ	संजय तामाङ		5	Reconstruction	पुनर्निर्माण
4	Roshi	7	श्री गज बहादुर तामाङ	विल बहादुर तामाङ		5	Reconstruction	पुनर्निर्माण
5	Roshi	7	श्री च्याङ्वा तामाङ	काले तामाङ		3	Major Retrofit (Category 2)	प्रबलीकरण(समुह २)
6	Roshi	7	श्री मान बहादुर लोप्चन	मानध्वज लोप्चन	The beneficiary has another house fully damage.	5	Reconstruction	पुनर्निर्माण
7	Roshi	7	श्री कृष्ण बहादुर	तारा माया तामाङ्नि		4	Reconstruction	पुनर्निर्माण
8	Roshi	7	श्री इन्द्र सिं तामाङ	देवराज लामा		5	Reconstruction	पुनर्निर्माण
9	Roshi	7	श्री द्वारिकानाथ गाँतम	अमन्ती नाथ गाँतम		1	Not Required	आवश्यक छैन
10	Roshi	7	श्री चन्द्र बहादुर तामाङ	चन्द्र माया तामाङनी		4	Reconstruction	पुनर्निर्माण
11	Roshi	7	श्री बीरदन	पुतली तामाङ		4	Reconstruction	पुनर्निर्माण
12	Roshi	7	श्री इमान सि तामाङ	तिमाल सि तामाङ		1	Not Required	आवश्यक छैन
13	Roshi	7	श्री राम प्रसाद अधिकारी	पुरुषोत्तम अधिकारी		1	Not Required	आवश्यक छैन
14	Roshi	7	श्री नरहरी अधिकारी	शम्भु प्रसाद अधिकारी		5	Reconstruction	पुनर्निर्माण
15	Roshi	7	श्री राम प्रसाद अधिकारी	शिवहरि अधिकारी		1	Not Required	आवश्यक छैन
16	Roshi	7	श्री टेक नाथ प्याकुरेल	माधव प्रसाद प्याकुरेल		2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
17	Roshi	7	श्री पूर्ण मान तामाङ	मोहन लाल तामाङ		4	Reconstruction	पुनर्निर्माण
18	Roshi	7	श्री राजमान तामाङ	धन बहादुर लामा		4	Reconstruction	पुनर्निर्माण
19	Roshi	7	श्री लाल बहादुर तामाङ	धनबहादुर तामाङ		4	Reconstruction	पुनर्निर्माण
20	Roshi	7	श्री इमान सि तामाङ	इन्द्र धवज तामाङ		4	Reconstruction	पुनर्निर्माण
21	Roshi	7		Chandra Prasad Gautam		1	Not Required	आवश्यक छैन
22	Roshi	7		Hark Maya Gautam		3	Major Retrofit (Category 2)	प्रबलीकरण(समुह २)
23	Roshi	7	श्री इन्द्र बहादुर	डिल बहादुर शाही		2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
24	Roshi	7	श्री भिन बहादुर कामी	चमेली वि क		1	Not Required	आवश्यक छैन
25	Roshi	7	श्री तेज बहादुर कामी	रेखमान वि क		1	Not Required	आवश्यक छैन
26	Roshi	7	श्री रेखमान वि क	चन्द्रबहादुर वि क		1	Not Required	आवश्यक छैन
27	Roshi	7	श्री वल बहादुर वि क	कुमारी वि क		1	Not Required	आवश्यक छैन
28	Roshi	7	श्री यक बहादुर राक्से ठकुरी	किरण कुमार राक्से ठकुरी		1	Not Required	आवश्यक छैन
29	Roshi	7	श्री युवराज ठकुरी	मञ्जु ठकुरी		1	Not Required	आवश्यक छैन
30	Roshi	7	श्री शेर बहादुर गाँतम	कमल बहादुर गाँतम		2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
31	Roshi	7	श्री जिवनाथ गौतम	कान्छा गौतम		2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
32	Roshi	7	श्री शेर बहादुर गाँतम	भुवन बहादुर गाँतम		5	Reconstruction	पुनर्निर्माण
33	Roshi	7	श्री साइला सिं तामाङ	आशारानी लामा		5	Reconstruction	पुनर्निर्माण
34	Roshi	7	श्री साईला सिं तामाङ	लालीमाया तामाङनी		5	Reconstruction	पुनर्निर्माण
35	Roshi	7	श्री सुब्बा तामाङ	राजु तामाङ		5	Reconstruction	पुनर्निर्माण
36	Roshi	7	श्री दुर्गा प्रसाद न्याँपाने	विष्णु प्रसाद न्याँपाने		4	Reconstruction	पुनर्निर्माण
37	Roshi	7	श्री धर्मलाल श्रेष्ठ	बुद्धीलाल श्रेष्ठ		5	Reconstruction	पुनर्निर्माण
38	Roshi	7	श्री चन्द्र सिं	वम बहादुर लामा	Damaged, debris removed and re-built (or re- building)	5	Reconstruction	पुनर्निर्माण



क्र.स	स्थानिय तह	वडा नं.	बुबा/श्रीमानको नाम	लाभग्राहीको नाम	comments	damage_grade	grade_category	श्रेणी वर्ग
1	Roshi	8	श्री लिला बहादुर कामी	अनन्द बहादुर कामी		4	Reconstruction	पुनर्निर्माण
2	Roshi	8	श्री कृष्णमान लामा	वौघद सिं लामा		5	Reconstruction	पुनर्निर्माण
3	Roshi	8	श्री इन्द्र बहादुर ठकुरी	प्रविन मल्ल		1	Not Required	आवश्यक छैन
4	Roshi	8	श्री पुर्ण बहादुर लामा	एसीड लामा		5	Reconstruction	पुनर्निर्माण
5	Roshi	8	श्री मानविर लामा	कामी सिं तामाङ		1	Not Required	आवश्यक छैन
6	Roshi	8	श्री देवन्त राम तामाङ	जित बहादुर तामाङ		5	Reconstruction	पुनर्निर्माण
7	Roshi	8	श्री इन्द्र बहादुर	गणेश बहादुर		4	Reconstruction	पुनर्निर्माण
8	Roshi	8	श्री रत्नमान लामा	जयमान लामा		1	Not Required	
9	Roshi	8	श्री धरी बहादुर मगर	पुर्ण बहादुर मगर		4	Reconstruction	पुनर्निर्माण
10	Roshi	8	श्री बुद्धिमान कामी	अमर कामी	As per surveyor, the building is repaired and occupied. where Upper side wall was completely damaged with effect on floor	3	Major Retrofit (Category 2)	प्रबलीकरण(समुह २)
11	Roshi	8	श्री सार्की तामाङ	आसुली तामाङनी		1	Not Required	आवश्यक छैन
12	Roshi	8	श्री महिला घिसिङ	नेत्र बहादुर तामाङ	As per selection "Damaged, debris removed and re-built (or re-building)"	5	Reconstruction	पुनर्निर्माण
13	Roshi	8	श्री कुल बहादुर मगर	भिम बहादुर मगर		1	Not Required	आवश्यक छैन
14	Roshi	8	श्री इन्द्र बहादुर मल्ल	जनक कुमरी मल्ल		1	Not Required	आवश्यक छैन
15	Roshi	8	श्री देव राज ठकुरी	विष्णु कुमारी ठकुरी		1	Not Required	आवश्यक छैन
16	Roshi	8	श्री नर बहादुर ठकुरी	देवराज ठकुरी		1	Not Required	आवश्यक छैन
17	Roshi	8	श्री धन बहादुर मगर	गोमा मगर		5	Reconstruction	पुनर्निर्माण
18	Roshi	8	श्री नुवु लामा	टेक बहादुर लामा		4	Reconstruction	पुनर्निर्माण
19	Roshi	8	श्री छेडुप लामा	कान्छी माया तामाङ		4	Reconstruction	पुनर्निर्माण



क्र.स	स्थानिय तह	वडा नं.	बुबा/श्रीमानको नाम	लाभग्राहीको नाम		damage_grade	grade_category	श्रेणी वर्ग
1	Roshi	9	श्री मान बहादुर तामाङ	धन बहादुर तामाङ		3	Major Retrofit (Category 2)	प्रबलीकरण(समुह २)
2	Roshi	9	श्री खड्ग बहादुर	ओकील बहादुर ज्यु ठकुरी	The damage grade is OK. But the surveyor comment should be considered "The house has not damaged till now but it is adjacent to active landslide within 10m. Structurally the house is without damage till now but geologically it is unfit to stay."	1	Not Required	आवश्यक छैन
3	Roshi	9	श्री मैत सिंह तामाङ	डिमा दोर्जे तामाङ		4	Reconstruction	पुनर्निर्माण
4	Roshi	9	श्री दिल बहादुर कामी	चतुर सि कामी		4	Reconstruction	पुनर्निर्माण
5	Roshi	9	श्री कुल बहादुर मगर	खेल बहादुर मगर	DG3 recommended by surveyor is OK as per structural condition. Should consider surveyor comment "The lateral earth pressure from backside bulges out backside of building. The building is in 100 m away from major landslide area and also from backside landslide may occur in near future." Reviewer Recommendation: Geo technical Study and Investigation of Site is recommended.	3	Major Retrofit (Category 2)	प्रबलीकरण(समुह २)
6	Roshi	9	श्री थलबहादुर आचार्य	कुमार आचार्य		5	Reconstruction	पुनर्निर्माण
7	Roshi	9		(Bishal Lama)विशाल लामा		4	Reconstruction	पुनर्निर्माण
8	Roshi	9	श्री काजी लामा	बाबु तमाङ		5	Reconstruction	पुनर्निर्माण
9	Roshi	9	श्री लिलाराज ज्यु ठकुरी	प्रेम बहादुर ज्यु ठकुरी		5	Reconstruction	पुनर्निर्माण
10	Roshi	9	श्री लिला बहादुर	नन्द राज ठकुरी		1	Not Required	आवश्यक छैन
11	Roshi	9	श्री कापों लामा	साइला लामा		5	Reconstruction	पुनर्निर्माण
12	Roshi	9	श्री कृष्ण प्रसाद अधिकारी	शीव कुमार अधिकारी		3	Major Retrofit (Category 2)	
13	Roshi	9	श्री धावा लामा	भिम बहादुर तामाङ		4	Reconstruction	पुनर्निर्माण
14	Roshi	9	श्री धन बहादुर यस्माली	खिलराज यस्माली	DG2 recommended by surveyor is OK as per structural condition. But its recommended to consider surveyor comment: 1.The lateral earth pressure from back side bulges out the back wall Reviewer Recommendation: Geo technical Study and Investigation of Site is recommended.	2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
15	Roshi	9	श्री चन्द्र लाल तामाङ	आइ सिंह तामाङ		4	Reconstruction	पुनर्निर्माण
16	Roshi	9	श्री कापों लामा	साइला लामा		5	Reconstruction	पुनर्निर्माण
17	Roshi	9	श्री कापों लामा	पेमा घ्योज लामा		5	Reconstruction	पुनर्निर्माण
18	Roshi	9	श्री माइला तामाङ	ज्ञान बहादुर तामाङ		5	Reconstruction	पुनर्निर्माण
19	Roshi	9		Dudhiraaj Jyu Thakuri Jyu Thakuri		5	Reconstruction	पुनर्निर्माण
20	Roshi	9	श्री इन्द्र प्रसाद हुमागाई	हुत राज हुमागाई		5	Reconstruction	पुनर्निर्माण
21	Roshi	9	श्री दमै सिंह तामाङ	कान्छिमाया तामाङ		4	Reconstruction	पुनर्निर्माण
22	Roshi	9	श्री थलबहादुर आचार्य	गणेश आचार्य		5	Reconstruction	पुनर्निर्माण
23	Roshi	9	श्री फाल्गुणी प्रसाद कोईराला	मिन प्रसाद कोईराला		5	Reconstruction	पुनर्निर्माण
24	Roshi	9	श्री कमान सिंह तामाङ	जीत बहादुर तामाङ		5	Reconstruction	पुनर्निर्माण
25	Roshi	9	श्री वीर बहादुर तामाङ	श्री कुमार तामाङ		5	Reconstruction	पुनर्निर्माण
26	Roshi	9	श्री भिम बहादुर तामाङ	कुन्साङ तामाङ		5	Reconstruction	पुनर्निर्माण
27	Roshi	9	श्री भक्त बहादुर शाही	तारा बहादुर शाही		4	Reconstruction	पुनर्निर्माण



28	Roshi	9	श्री चन्द्र बहादुर लामा	लाल बहादुर लामा		5	Reconstruction	पुनर्निर्माण
29	Roshi	9		Chhetra Bahdur Tamang		5	Reconstruction	पुनर्निर्माण
30	Roshi	9	श्री नर बहादुर आचार्य	थल बहादुर आचार्य		5	Reconstruction	पुनर्निर्माण
31	Roshi	9	श्री बालकृष्ण मैनाली	दिपेन्द्र प्रसाद मैनाली		5	Reconstruction	पुनर्निर्माण
32	Roshi	9	श्री दान नोर्बु तामाङ	छोईसाङ तामाङ्नी		4	Reconstruction	पुनर्निर्माण
33	Roshi	9	श्री फाल्गुणी प्रसाद कोइराला	विश्वराज कोइराला		4	Reconstruction	पुनर्निर्माण
34	Roshi	9	श्री धोकर पाराङ	सन्च माया लामा		5	Reconstruction	पुनर्निर्माण
35	Roshi	9	श्री लक्ष्मण तामाङ	छिरिङ तामाङ		5	Reconstruction	पुनर्निर्माण
36	Roshi	9	श्री कर्म दुन्दुप लामा	सत्य मान लामा		5	Reconstruction	पुनर्निर्माण
37	Roshi	9	श्री कर्म दुन्दुप लामा	गोपाल लामा		5	Reconstruction	पुनर्निर्माण
38	Roshi	9	श्री हर्क बहादुर लामा	गणेश लामा		5	Reconstruction	पुनर्निर्माण
39	Roshi	9	श्री चक्र बहादुर	कारचुङ लामा		1	Not Required	आवश्यक छैन
40	Roshi	9	श्री कृष्ण कुमार लामा	लक्ष्मी तामाङ्नी		4	Reconstruction	पुनर्निर्माण
41	Roshi	9	श्री जितेन्द्र पाल तामाङ	सुर्य पाल तामाङ		5	Reconstruction	पुनर्निर्माण
42	Roshi	9	श्री कर्मद दुन्दुप लामा	कमल लामा		5	Reconstruction	पुनर्निर्माण
43	Roshi	9	श्री कलसाङ लामा	दावा लामा		5	Reconstruction	पुनर्निर्माण
44	Roshi	9	श्री कर्म दुन्दुप लामा	संग्राम सिंह लामा		5	Reconstruction	पुनर्निर्माण
45	Roshi	9	श्री अक्कल बहादुर लामा	बेली कुमारी लामा		5	Reconstruction	पुनर्निर्माण
46	Roshi	9	श्री भरत सिंह लामा	सुर्य लामा		5	Reconstruction	पुनर्निर्माण
47	Roshi	9	श्री राम सिंह लामा	अकटर ग्याल्चो दोङ		5	Reconstruction	पुनर्निर्माण



क्र.स	स्थानिय तह	वडा नं.	बुबा/श्रीमानको नाम	लाभप्राहीको नाम	comments	damage_grade	grade_category	श्रेणी वर्ग
1	Roshi	10	श्री मगर सिं वाइबा	उर्लि	have other house with fully damage.	5	Reconstruction	पुनर्निर्माण
2	Roshi	10	श्री मान बहादुर लामा	काईला लामा	have other house with fully damaged.	5	Reconstruction	पुनर्निर्माण
3	Roshi	10	श्री कामी सिं लामा	अर्चमान लामा	Not enough evidence for DG4, recommended to DG3. Have other house with partial damage.	4	Reconstruction	पुनर्निर्माण
4	Roshi	10	श्री पुर्णविर श्रेष्ठ	कुमार श्रेष्ठ	The damage grade is accepted as its repaired. But as per site condition GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	आवश्यक छैन
5	Roshi	10	श्री पुर्णविर श्रेष्ठ	राजकुमार श्रेष्ठ		5	Reconstruction	पुनर्निर्माण
6	Roshi	10	श्री रित्त बहादुर शाही	दिपक शाही	Damaged but debris not cleared. have other house with full damage.	5	Reconstruction	पुनर्निर्माण
7	Roshi	10	श्री हस्त बहादुर शाही	बल बहादुर शाही		5	Reconstruction	पुनर्निर्माण
8	Roshi	10	श्री तानचन लामा	टेक बहादुर लामा	have other house with fully damage.	5	Reconstruction	पुनर्निर्माण
9	Roshi	10	श्री तोरबहादुर हमाल	अबिस हमाल	Damaged, debris removed and re-built (or re- building). The pictures of the house was of newly built house.	5	Reconstruction	पुनर्निर्माण
10	Roshi	10	श्री हस्त बहादुर श्रेष्ठ	चन्द्र बहादुर श्रेष्ठ		5	Reconstruction	पुनर्निर्माण
11	Roshi	10	श्री एक बहादुर खामी मगर	शेर बहादुर खामी मगर		5	Reconstruction	पुनर्निर्माण
12	Roshi	10	श्री साइला तामाङ	भक्त बहादुर लामा	Damaged, Building has been completely covered/carried away by landslide/debris.	5	Reconstruction	पुनर्निर्माण
13	Roshi	10	श्री पदम बहादुर हमाल	देवी बहादुर हमाल		3	Major Retrofit (Category 2)	प्रबलिकरण(समुह २)
14	Roshi	10	श्री बुद्धिमान तामाङ	डेमा तामाङ		5	Reconstruction	पुनर्निर्माण
15	Roshi	10	श्री वृष बहादुर मगर	शिव बहादुर मगर	The damage grade DG2 is OK. But as per surveyor "previously due to heavy rainfall damage of the courtyard but he has repaired." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	2	Minor Retrofit (Category 1)	प्रबलिकरण(समुह १)
16	Roshi	10	श्री मिनबहादुर रेग्मी	सागर रेग्मी		1	Not Required	
17	Roshi	10	श्री हर्क बहादुर भुजेल	ओमबहादुर भुजेल	the building has already been repaired	3	Major Retrofit (Category 2)	प्रबलिकरण(समुह २)
18	Roshi	10	श्री धिम बहादुर साकी	बद्री साकी	The building was completely covered with debris and later it was removed.Now the new mud masonry building is being built in site.	5	Reconstruction	पुनर्निर्माण
19	Roshi	10	श्री सिता शाही	राजाराम शाही		5	Reconstruction	पुनर्निर्माण
20	Roshi	10	श्री पुर्ण प्रसाद चालिसे	मानिष चालिसे		3	Major Retrofit (Category 2)	प्रबलिकरण(समुह २)
21	Roshi	10	श्री गज बहादुर क्याफ्फाकी	भुवन क्याफ्फाकी मगर	As per surveyor "Site is at risk of landslide." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	आवश्यक छैन



22	Roshi	10	श्री गणेश यस्माली	सानु माया यस्माली	As per surveyor "Site is at risk of landslide." GEOTECHNICAL AND GEOLOGICAL INVESTIGATION OF SITE IS RECOMMENDED.	1	Not Required	आवश्यक छैन
23	Roshi	10	श्री दल बहादुर पुतामी	गुण्डा बहादुर मगर	The previous building was completely collapsed and a new building was recently built. The family were not separated previously but after construction of the new house 2 Family are living separately under the same roof(father and son's family).	5	Reconstruction	पुनर्निर्माण
24	Roshi	10	श्री टेक बहादुर यस्माली	लीला बाहादुर यस्माली		5	Reconstruction	पुनर्निर्माण
25	Roshi	10	श्री कृष्ण बहादुर ठकुरी	रामहरी ठकुरी		5	Reconstruction	पुनर्निर्माण
26	Roshi	10	श्री दावा सि तामाङ	प्रमोद तामाङ	The building is completely collapsed. The area is at high risk of landslides.	5	Reconstruction	पुनर्निर्माण
27	Roshi	10	श्री हेमन्त ज्यू	अनन्त कुमार ज्यू ठकुरी		4	Reconstruction	पुनर्निर्माण



क्र.स	स्थानिय तह	वडा नं.	बुबा/श्रीमानको नाम	लाभग्राहीको नाम	comments	damage grade	grade_category	श्रेणी वर्ग
1	Roshi	11	श्री देव कुमार स्याङ्तान	विष्णु कुमार स्याङ्तान		4	Reconstruction	पुनर्निर्माण
2	Roshi	11		(Hari Prasad Mainali)हरि प्रसाद मैनाली		5	Reconstruction	पुनर्निर्माण
3	Roshi	11		Bhair Bahadur Tamang		3	Major Retrofit (Category 2)	प्रबलीकरण(समुह २)
4	Roshi	11	श्री कुल बहादुर यस्माली	कालीका माया यस्माली		2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
5	Roshi	11	श्री रबिलाल रेग्मी	काली प्रसाद रेग्मी	debris fall from room to inside building.	5	Reconstruction	पुनर्निर्माण
6	Roshi	11	श्री दान बहादुर मगर	राम बहादुर मगर	Surveyor has upload relevant photo (stating : back of building)	5	Reconstruction	पुनर्निर्माण
7	Roshi	11	श्री सानु इन्द्र बहादुर सिङ्ग	लक्ष्मण सिङ्ग		5	Reconstruction	पुनर्निर्माण
8	Roshi	11	श्री मोहन बहादुर मगर	दिल कुमार मगर		2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
9	Roshi	11	श्री लक्ष्मण सिङ्ग	पसपती सिङ्ग		5	Reconstruction	पुनर्निर्माण
10	Roshi	11	श्री सुब्बा पुलामी मगर	नबराज पुलामी मगर		5	Reconstruction	पुनर्निर्माण
11	Roshi	11		(Surath Lama) सुरथ लामा		5	Reconstruction	पुनर्निर्माण
12	Roshi	11		(Kajee Maan Tamang) काजी मान तामाङ	have other house with no damage.	2	Minor Retrofit (Category 1)	प्रबलीकरण(समुह १)
13	Roshi	11	श्री कान्छा तामाङ	रेशम तामाङ	collapsed. have other house with full damage., collapsed. have other house with full damage.	5	Reconstruction	पुनर्निर्माण
14	Roshi	11	श्री पासाङ तामाङ	छिरिङ तामाङ		5	Reconstruction	पुनर्निर्माण
15	Roshi	11	श्री दमै सि तामाङ	सुबास तामाङ	partial damage in one side wall but re-built	4	Reconstruction	पुनर्निर्माण
16	Roshi	11	श्री मान कुमार श्रेष्ठ	देवेन्द्र श्रेष्ठ	landslide area.	5	Reconstruction	पुनर्निर्माण
17	Roshi	11	श्री शिव लाल श्रेष्ठ	सीता देवी श्रेष्ठ		5	Reconstruction	पुनर्निर्माण
18	Roshi	11	श्री सुरेन्द्र कुमार कर्माचार्य	केलास कर्माचार्य		5	Reconstruction	पुनर्निर्माण
19	Roshi	11	श्री याङ्जि शेर्पा	छिरीङगमा शेर्पा		5	Reconstruction	पुनर्निर्माण
20	Roshi	11	श्री प्रेम बहादुर तामाङ	पशुपति कुमार स्याङ्तान		5	Reconstruction	पुनर्निर्माण
21	Roshi	11	श्री प्रेम बहादुर आले	गणेश बहादुर आले		5	Reconstruction	पुनर्निर्माण
22	Roshi	11	श्री काजी मान तामाङ	जगत मान तामाङ		5	Reconstruction	पुनर्निर्माण
23	Roshi	11	श्री सुर्य बहादुर तामाङ	नानी बानु तामाङ		5	Reconstruction	पुनर्निर्माण
24	Roshi	11	श्री सुर्य लाल श्रेष्ठ	राज कुमार श्रेष्ठ	Damaged, Building has been completely covered/carried away by landslide/debris	5	Reconstruction	पुनर्निर्माण
25	Roshi	11	श्री केदार कुमार श्रेष्ठ	सुनिता श्रेष्ठ	Damaged, Building has been completely covered/carried away by landslide/debris	5	Reconstruction	पुनर्निर्माण

